

City of Joseke Grove

Infrastructure Inspection Summary

Inspection Date: September 15, 2025

Structures Reviewed

North Fork Bridge - Condition: Fair. Recommended action: Deck resurfacing within 3 years.

East Briarwood Pedestrian Bridge - Condition: Poor. Recommended action: Structural reinforcement required.

Maidnach Park Footbridge - Condition: Closed pending repair.